

NOTICE TO MARINERS



Notice to Mariners associated with construction activities on Seagreen Offshore Wind Farm

Date of Issue	27-12-21	Notice Number	17-2021 – Rev 4
---------------	----------	---------------	-----------------

Seagreen Export Cable Nearshore Protection works – Revision 4

Contact Details for Marine Coordination and Fisheries Liaison

The following contact can provide more information if required:

Telephone Number (Day Operations)	+44 (0) 333 344 5255
Email for Marine Coordinator	seagreenmarinecoordination@sse.com
Address	Seagreen Wind Energy Ltd 1 Waterloo Street Glasgow Glasgow G2 6AY

Fisheries liaison is coordinated by Brown and May Marine Ltd. For all fisheries enquiries, Alex Winrow-Giffin is primary contact:

Telephone Number	+44 (0) 1379872144
Mobile number	+44 (0) 7760 160039
Email	Alex@brownmay.com
Address	Brown and May Marine Progress Way Mid Suffolk Business Park Eye, Suffolk IP23 7HU

1. Area of Planned Activity.

Nearshore export cable protection works continue at the Seagreen Offshore Wind Farm export cable landfall site at Carnoustie, Angus. Due to recent storm damage remedial works require to be undertaken. Six temporary anchors will be deployed in advance of the three semi-submersible cable protection pipes being re-positioned. Further details and coordinates of the anchors are shown below.

NOTICE TO MARINERS



Fig 1.




Fig 2 – Current pipe end locations.

NOTICE TO MARINERS




Fig 3 – Temporary anchors

Pipe end 1	56°29.520	002°42.826	Marked with buoy	Rocknet attached
Pipe end 2	56°29.525	002°42.820	Marked with buoy	
Mooring point 1	56°29.42	002°42.68	Marked with buoy	
Mooring point 2	56°29.43	002°42.62	Marked with buoy	
Mooring point 3	56°29.46	002°42.63	Marked with buoy	
Mooring point 4	56°29.45	002°42.68	Marked with buoy	
Stored Rocknet	56°29.43	002°42.66	Marked with buoy	
Rocknet	56°29.412	002°42.750	Marked with buoy	

Table 1.

Anchor 1	56° 29.472' N	2° 42.666' W	Marked with day-glo pellet buoy
Anchor 2	56° 29.442' N	2° 42.663' W	Marked with day-glo pellet buoy
Anchor 3	56° 29.436' N	2° 42.659' W	Marked with day-glo pellet buoy
Anchor 4	56° 29.430' N	2° 42.656' W	Marked with day-glo pellet buoy
Anchor 5	56° 29.418' N	2° 42.734' W	Marked with day-glo pellet buoy
Anchor 6	56° 29.436' N	2° 42.747' W	Marked with day-glo pellet buoy

Table 2 – Anchor coordinates

2. Activity Description.

On behalf of Seagreen Wind Energy Ltd, Nexans Norway Dykkerteknikk AS continues to deliver nearshore export cable protection services and diving assistance in preparation for the pull-in of three export cables

Due to recent storm damage to the three self-submersible cable protection pipes and rockbag temporary moorings remedial works require to take place. The known locations of two of the pipe

NOTICE TO MARINERS

ends and rock-bags are shown in table 1 and fig 2. Prior to the pipes being re-located to their correct position 6 temporary anchors will be deployed. The pipe ends will then be secured to the anchors. The anchors will all be marked by day-glo pellet buoys. Coordinates of the anchors are shown in table 2 and fig 3. All works will be undertaken by the DSV Sophie at a date to be confirmed, details below.

Vessel Name – MPV Sophie	
General Description and Dimensions:	Multi-Purpose vessel. 14.9m x 7.0m x 1.0m
Call Sign:	LK7943
MMSI:	258003500
Direct Bridge/ Masters Number	+47 928 35 222
Onshore Representative:	anders@dykkerteknikk.no ; halvor@dykkerteknikk.no
	

4. General Safety Advice

All vessels engaged in the nearshore protection work will exhibit appropriate lights and shapes prescribed by the International Regulations for Preventing Collisions at Sea; relative to their operations. All vessels engaged in the activity will also transmit an Automatic Identification System (AIS) message.

MARINERS ARE REMINDED to navigate with caution and keep continued watch on VHF Ch. 70/16 when navigating the area

5. Distribution List

A central list of recipients is maintained by the Marine Coordinator; if you are not the appropriate recipient of these notices, or do not wish to receive the notices in the future, please contact us at the address included in Section 1 of this notice.