

NOTICE TO MARINERS



Notice of works associated with construction activities on Seagreen Offshore Wind Farm

Date of Issue	22/03/2022	Notice Number	07/2022
---------------	------------	---------------	---------

Seagreen Offshore Wind Farm – Site demarcation buoy repairs.

Contact Details for Marine Coordination and Fisheries Liaison

The following contact can provide more information if required:

Telephone Number, 24/7	+44 (0) 333 344 5255
Duty Marine Coordinator	seagreenmarinecoordination@sse.com
Address	Seagreen Wind Energy Ltd, Inchbraoch House Montrose Port Authority, South Quay Ferryden, Montrose, Angus DD10 9SL.

Fisheries liaison is coordinated by Brown and May Marine Ltd. For all fisheries enquiries, John Watt is primary contact:

Telephone Number	+44 (0) 1379872144
Mobile number	+44 (0) 7590 880746
Email	John.Watt@Brownmay.com
Address	Brown and May Marine Progress Way Mid Suffolk Business Park Eye, Suffolk IP23 7HU

1. Area of planned activity.

Repairs will be carried out on four damaged site demarcation buoys on the boundary of the Seagreen Offshore Wind Farm, coordinates of the damaged buoys and their locations are shown below in table 1 and fig 1 and highlighted in yellow, checks will be conducted on a number of the remaining demarcation buoys.

ID	Latitude (DDM WGS 84)	Longitude (DDM WGS 84)
North Cardinal Mark 1 - AIS	56° 40.578' N	1° 56.746' W
North Cardinal Mark 2	56° 40.710' N	1° 38.857' W
East Cardinal Mark 1 - AIS	56° 38.616' N	1° 33.305' W
East Cardinal Mark 2 - AIS	56° 31.848' N	1° 29.282' W
South Cardinal Mark - AIS	56° 30.798' N	1° 56.137' W
Special Mark 1	56° 40.632' N	1° 50.517' W

NOTICE TO MARINERS

ID	Latitude (DDM WGS 84)	Longitude (DDM WGS 84)
Special Mark 2	56° 40.746' N	1° 44.622' W
Special Mark 3	56° 35.232' N	1° 30.473' W
Special Mark 4	56° 31.374' N	1° 35.618' W
Special Mark 5	56° 31.107' N	1° 42.151' W
Special Mark 6	56° 30.870' N	1° 49.017' W
Special Mark 7	56° 33.774' N	1° 57.149' W
Special Mark 8	56° 37.176' N	1° 57.182' W

Table 1 – Demarcation buoy coordinates.




Fig 1 – Demarcation buoy locations.


2. Activity Description.

On behalf of Seagreen Wind Energy, Seaway 7 will conduct repair works on four damaged site demarcation buoys, the coordinates and locations of the buoys are shown above in table 1 and fig 1. The works will be conducted by the Workboat Forth Warrior which is expected on site on or around Thursday the 24th of March to commence the works. Details of the Forth Warrior are shown below.

3. Vessel Details

Vessel Name – Forth Warrior	
General Description and Dimensions:	Workboat – LOA 27.3m x 11.5 beam
Call Sign:	2JHR8
MMSI:	235116011
Direct Bridge/ Masters Number	TBC
Onshore Representative:	George Cooper George.cooper@seaway7.com

NOTICE TO MARINERS



4. General Safety Advice

All vessels involved in construction activities will exhibit appropriate lights and day-time shapes prescribed by the International Regulations for Preventing Collisions at Sea, relative to operations. The vessel will also transmit an Automatic Identification System (AIS) message.

4. Safety Zones

Following consideration by Scottish government ministers it has been agreed that during the construction phases of the Seagreen development mandatory rolling 500m safety zones will be established around each Wind Turbine Generator and/or their foundations whilst construction works are in progress, as indicated by the presence of a construction vessel. The safety zones will be triggered whenever a vessel is on station at a WTG and undertaking construction activities.

In addition, mandatory pre commissioning 50m safety zones will be established around each Wind Turbine Generator and/or their foundations when construction works have been completed but prior to Wind Farm commissioning or where construction works have only been partially completed. These safety zones will be active at any structure during the construction phase where a construction vessel is not present at a Wind Turbine Generator.

MARINERS ARE REMINDED to navigate with caution and keep continued watch on VHF Ch.70/16 when navigating the area.

5. Distribution List

A central list of recipients is maintained by the Marine Coordinator; if you are not the appropriate recipient of these notices, or do not wish to receive the notices in the future, please contact us at the address shown in this notice.